

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen	SK	<1.0	-	-	None	-	-
Gym	WF	<1.0	-	-	None	-	-
Nurses BR	SK	1.7	-	-	None	-	-
Boys BR by RM 12 @ (A)	SK	<1.0	-	-	None	-	-
Boys BR by RM 12 @ (C)	SK	1	-	-	None	-	-
Boys BR by RM 12 @ (D)	SK	<1.0	-	-	None	-	-
CC by RM 12	SS	1	-	-	None	-	-
Mens BR	SK	1.5	-	-	None	-	-
<b>Mens BR</b>	<b>SS</b>	<b>42</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
3rd Grade Wing Girls BR @ (A)	SK	<1.0	-	-	None	-	-
3rd Grade Wing Girls BR @ (B)	SK	<1.0	-	-	None	-	-
3rd Grade Wing Hallway	WF	<1.0	-	-	None	-	-
<b>Circulation RM</b>	<b>SK</b>	<b>23</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
RM 6	WF	<1.0	-	-	None	-	-
RM 6	SK	<1.0	-	-	None	-	-
RM 7	WF	1.5	-	-	None	-	-
RM 7	SK	<1.0	-	-	None	-	-
RM 8	WF	<1.0	-	-	None	-	-
RM 8	SK	<1.0	-	-	None	-	-
Hallway by RM 11	WF	<1.0	-	-	None	-	-
Unisex BR by Stage	SK	<1.0	-	-	None	-	-
Hallway by Stage	WF	4.2	-	-	None	-	-
RM 21 BR	SK	<1.0	-	-	None	-	-

**Lead in Drinking Water Test Results**

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 22 BR	SK	<1.0	-	-	None	-	-
RM 19 BR	SK	<1.0	-	-	None	-	-
RM 20 BR	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Portable A BR	SK	2.9	-	-	None	-	-
Portable B BR	SK	<2.5	-	-	None	-	-
Portable D BR	SK	6.1	-	-	None	-	-
Portable C BR	SK	<2.5	-	-	None	-	-
CC by RM 6	SS	<2.5	-	-	None	-	-
Ladies BR by RM 6 @ (A)	SK	<2.5	-	-	None	-	-
Ladies BR by RM 6 @ (B)	SK	<2.5	-	-	None	-	-
Hallway by RM 9	WF	<2.5	-	-	None	-	-
Boys BR by RM 10	SK	3.4	-	-	None	-	-
CC by RM 10	SS	4.1	-	-	None	-	-
Teachers Lounge	SK	<2.5	-	-	None	-	-
Boys BR by RM 23	SK	<2.5	-	-	None	-	-
Ladies BR by RM 23 @ (A)	SK	<2.5	-	-	None	-	-
Ladies BR by RM 23 @ (B)	SK	<2.5	-	-	None	-	-
CC by RM 27	SS	<2.5	-	-	None	-	-
RM 21	WF	14	-	-	None	-	-
RM 21	SK	<2.5	-	-	None	-	-
<b>RM 18</b>	<b>SK</b>	<b>20</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
Hallway by RM 19	WF	<2.5	-	-	None	-	-
<b>RM 19</b>	<b>WF</b>	<b>152</b>			<b>FR</b>	<b>Completed FR</b>	<b>6</b>
RM 19	SK	6.6	-	-	None	-	-
RM 20	SK	12	-	-	None	-	-
Hallway by RM 23	WF	<2.5	-	-	None	-	-

**Lead in Drinking Water Test Results**

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Mens BR by RM 26 @ (A)	SK	5.7	-	-	None	-	-
Mens BR by RM 26 @ (B)	SK	<2.5	-	-	None	-	-
Media Center	SK	<2.5	-	-	None	-	-
Nurses BR	SK	<2.5	-	-	None	-	-
Kitchen	SK	<2.5	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Sink	SPRAY	<2.5	-	-	None	-	-
Hall by RM 28	WF	<2.5	-	-	None	-	-
CC by RM 28	SS	<2.5	-	-	None	-	-
Girls BR by RM 28 @ (A)	SK	<2.5	-	-	None	-	-
Girls BR by RM 28 @ (B)	SK	<2.5	-	-	None	-	-
RM 28	SK	<2.5	-	-	None	-	-
RM 31	SK	<2.5	-	-	None	-	-
Hall by RM 31	WF	<2.5	-	-	None	-	-
RM 38 Bubbler	WF	6.2	-	-	None	-	-
RM 38	SK	8.1	-	-	None	-	-
2nd Fl. Boys BR by RM 38	SK	<2.5	-	-	None	-	-
2nd Fl. CC by RM 38	SS	<2.5	-	-	None	-	-
2nd Fl. Boys Gang BR by RM 38 @ (A)	SK	<2.5	-	-	None	-	-
2nd Fl. Boys Gang BR by RM 38 @ (B)	SK	5.1	-	-	None	-	-
<b>RM 30</b>	<b>SK</b>	<b>75</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
RM 40	SK	3.5	-	-	None	-	-
<b>RM 41</b>	<b>SK</b>	<b>16</b>			<b>FR</b>	<b>SIGN</b>	<b>6.9</b>
RM 42	SK	<2.5	-	-	None	-	-
RM 37 Bubbler	WF	<2.5	-	-	None	-	-
RM 37	SK	<2.5	-	-	None	-	-
Faculty Lounge	SK	<2.5	-	-	None	-	-
RM 35	SK	3.6	-	-	None	-	-
RM 33	SK	9.3	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
<b>CC by RM 33</b>	<b>SS</b>	<b>21</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
Girls BR by RM 33 @ (A)	SK	<2.5	-	-	None	-	-
Girls BR by RM 33 @ (B)	SK	<2.5	-	-	None	-	-
<b>RM 32 Bubblers</b>	<b>WF</b>	<b>91</b>			<b>FR</b>	<b>Completed FR</b>	<b>12</b>
RM 32	SK	<2.5	-	-	None	-	-
Boys BR by RM 31 @ (A)	SK	<2.5	-	-	None	-	-
Boys BR by RM 31 @ (B)	SK	<2.5	-	-	None	-	-
Men/Women BR by RM 31	SK	<2.5	-	-	None	-	-
Nurses Office BR	SK	<2.5	-	-	None	-	-
Boys BR by RM 21 @ (A)	SK	<2.5	-	-	None	-	-
Boys BR by RM 21 @ (B)	SK	<2.5	-	-	None	-	-
CC by RM 21	SS	4.2	-	-	None	-	-
Girls BR by RM 25 @ (A)	SK	<2.5	-	-	None	-	-
Girls BR by RM 25 @ (B)	SK	<2.5	-	-	None	-	-
CC by RM 25	SS	<2.5	-	-	None	-	-
Music RM	SK	7.9	-	-	None	-	-
Phys. Ed. Office BR	SK	<2.5	-	-	None	-	-
Portable 3 BR	SK	<2.5	-	-	None	-	-
Portable 4 BR	SK	<2.5	-	-	None	-	-
Boys BR by RM 6	SK	<2.5	-	-	None	-	-
CC by RM 6	SS	<2.5	-	-	None	-	-
Faculty Lounge by RM 12	SK	<2.5	-	-	None	-	-
Girls BR by RM 12 @ (A)	SK	<2.5	-	-	None	-	-

**Lead in Drinking Water Test Results**

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girls BR by RM 12 @ (B)	SK	<2.5	-	-	None	-	-
CC by RM 12	SS	<2.5	-	-	None	-	-
Portable 1 BR	SK	<2.5	-	-	None	-	-
Portable 2 BR	SK	<2.5	-	-	None	-	-
Boiler RM	SK	11	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen 3 Bay @ (A)	SK	<2.5	-	-	None	-	-
Kitchen 3 Bay @ (B)	SK	<2.5	-	-	None	-	-
Kitchen 3 Bay @ (C)	SK	<2.5	-	-	None	-	-
Basement Girls BR @ (A)	SK	4.9	-	-	None	-	-
<b>Basement Girls BR @ (B)</b>	<b>SK</b>	<b>28</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
Basement Girls BR @ (C)	SK	<2.5	-	-	None	-	-
Basement Boys BR @ (A)	SK	<2.5	-	-	None	-	-
Basement Boys BR @ (B)	SK	3.4	-	-	None	-	-
Basement Boys BR @ (C)	SK	<2.5	-	-	None	-	-
Basement Boys BR @ (D)	SK	8.9	-	-	None	-	-
Basement CC	SS	<2.5	-	-	None	-	-
1st Fl. Boys BR @ (A)	SK	<2.5	-	-	None	-	-
1st Fl. Boys BR @ (C)	SK	<2.5	-	-	None	-	-
1st Fl. Boys BR @ (D)	SK	<2.5	-	-	None	-	-
1st Fl. CC	SS	3.5	-	-	None	-	-
Principal's Office BR	SK	<2.5	-	-	None	-	-
<b>1st Fl. Girls BR by Principal's Office @ (A)</b>	<b>SK</b>	<b>47</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
<b>1st Fl. Girls BR by Principal's Office @ (B)</b>	<b>SK</b>	<b>25</b>			<b>FR</b>	<b>SIGN</b>	<b>&lt;1.0</b>
1st Fl. Girls BR by Principal's Office @ (C)	SK	2.8	-	-	None	-	-
1st Fl. Girls BR by Principal's Office @ (D)	SK	<2.5	-	-	None	-	-
1st Fl. Boys BR by Principal's Office @ (A)	SK	<2.5	-	-	None	-	-
1st Fl. Boys BR by Principal's Office @ (B)	SK	<2.5	-	-	None	-	-
1st Fl. Boys BR by Principal's Office @ (C)	SK	<2.5	-	-	None	-	-



**Lead in Drinking Water Test Results**

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
1st Fl. Boys BR by Principal's Office @ (D)	SK	<2.5	-	-	None	-	-
CC by Nurses Office	SS	5.1	-	-	None	-	-
Nurses Office BR	SK	<2.5	-	-	None	-	-
Teachers RM BR	SK	<2.5	-	-	None	-	-
2nd Fl. Girls BR @ (A)	SK	5.4	-	-	None	-	-
2nd Fl. Girls BR @ (B)	SK	2.9	-	-	None	-	-
2nd Fl. Girls BR @ (C)	SK	7.3	-	-	None	-	-
2nd Fl. Girls BR @ (D)	SK	<2.5	-	-	None	-	-
<b>RM 12</b>	<b>SK</b>	<b>33</b>			<b>FR</b>	<b>SIGN</b>	<b>4.9</b>

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Handwash @ (A)	SK	4.4	-	-	None	-	-
Kitchen by Slicer	SK	<1.0	-	-	None	-	-
Kitchen 3 Compartment Sink @ (A)	SK	2.1	-	-	None	-	-
Kitchen 3 Compartment Sink @ (B)	SK	1	-	-	None	-	-
Kitchen Steamer @ (A)	SP	1.4	-	-	None	-	-
Kitchen Steamer @ (B)	SP	2.2	-	-	None	-	-
Kitchen Handwash @ (B)	SK	1.1	-	-	None	-	-
Serving Line North	SK	1.4	-	-	None	-	-
Serving Line South @ (A)	SK	8.2	-	-	None	-	-
Serving Line South @ (B)	SK	2.5	-	-	None	-	-
Kitchen BR	SK	<1.0	-	-	None	-	-
Café (North)	WF	<1.0	-	-	None	-	-
Café (South)	WF	3.9	-	-	None	-	-
Men's BR by C224 @ (A)	SK	<1.0	-	-	None	-	-
Men's BR by C224 @ (B)	SK	<1.0	-	-	None	-	-
Teacher's Lounge by C224	SK	<1.0	-	-	None	-	-
Teacher's Lounge by C224	SS	<1.0	-	-	None	-	-
Girl's BR @ (A)	SK	1.7	-	-	None	-	-
Girl's BR @ (B)	SK	1.8	-	-	None	-	-
Hallway by C208	WF	<1.0	-	-	None	-	-
Home C202 @ (A)	SK	<1.0	-	-	None	-	-
Home C202 @ (B)	SK	1.8	-	-	None	-	-
Home C202 @ (C)	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Home C202 @ (D)	SK	<1.0	-	-	None	-	-
Ladies BR by Pool Hallway @ (A)	SK	12	-	-	None	-	-
Ladies BR by Pool Hallway @ (B)	SK	7.7	-	-	None	-	-
Hallway by Pool	WF	<1.0	-	-	None	-	-
Men's BR by Pool Hallway @ (A)	SK	15	-	-	None	-	-
Men's BR by Pool Hallway @ (B)	SK	1.3	-	-	None	-	-
C103 Teacher's Station	SK	<1.0	-	-	None	-	-
C103 Table 1 @ (A)	SK	<1.0	-	-	None	-	-
C103 Table 1 @ (B)	SK	<1.0	-	-	None	-	-
C103 Table 4 @ (A)	SK	<1.0	-	-	None	-	-
C103 Table 4 @ (B)	SK	<1.0	-	-	None	-	-
C103 Table 5 @ (A)	SK	<1.0	-	-	None	-	-
C103 Table 6 @ (A)	SK	<1.0	-	-	None	-	-
C103 Table 6 @ (B)	SK	<1.0	-	-	None	-	-
C103 Table 7 @ (A)	SK	<1.0	-	-	None	-	-
C103 Table 7 @ (B)	SK	<1.0	-	-	None	-	-
C104	SK	<1.0	-	-	None	-	-
Men's BR by C104 @ (A)	SK	5.9	-	-	None	-	-
Men's BR by C104 @ (B)	SK	15	-	-	None	-	-
C102 Handwash	SK	1.6	-	-	None	-	-
C101 Teacher's Station	SK	<1.0	-	-	None	-	-
C101 Table 1 @ (A)	SK	<1.0	-	-	None	-	-
C101 Table 1 @ (B)	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
C101 Table 2 @ (A)	SK	<1.0	-	-	None	-	-
C101 Table 2 @ (B)	SK	<1.0	-	-	None	-	-
C101 Table 3 @ (A)	SK	<1.0	-	-	None	-	-
C101 Table 3 @ (B)	SK	<1.0	-	-	None	-	-
C101 Table 4 @ (A)	SK	<1.0	-	-	None	-	-
C101 Table 4 @ (B)	SK	<1.0	-	-	None	-	-
C101 Table 5 @ (A)	SK	3.2	-	-	None	-	-
C101 Table 5 @ (B)	SK	<1.0	-	-	None	-	-
Hallway by 105B	WF	<1.0	-	-	None	-	-
Men's BR by 105B @ (A)	SK	1	-	-	None	-	-
Men's BR by 105B @ (B)	SK	2.1	-	-	None	-	-
CC by 105B	SS	9.6	-	-	None	-	-
Training RM by Gym	SK	<1.0	-	-	None	-	-
Women's BR by @ (A)	SK	<1.0	-	-	None	-	-
Women's BR by @ (B)	SK	1.5	-	-	None	-	-
Nurse's Exam RM 1	SK	<1.0	-	-	None	-	-
Nurse	SK	<1.0	-	-	None	-	-
Nurse's Exam RM 2	SK	<1.0	-	-	None	-	-
Nurse's BR	SK	<1.0	-	-	None	-	-
Girl's LR Office	SK	<1.0	-	-	None	-	-
Girl's LR	WF	<1.0	-	-	None	-	-
Girl's LR BR @ (A)	SK	<1.0	-	-	None	-	-
Girl's LR BR @ (B)	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
<b>CC in Girl's LR</b>	<b>SS</b>	<b>24</b>			<b>FR</b>	<b>SIGN</b>	-
Gym Hallway	WF	<1.0	-	-	None	-	-
Gym Hallway Girl's BR @ (A)	SK	<1.0	-	-	None	-	-
Gym Hallway Girl's BR @ (B)	SK	<1.0	-	-	None	-	-
<b>Gym Hallway Girl's BR @ (C)</b>	<b>SK</b>	<b>67</b>			<b>FR</b>	<b>SIGN</b>	-
Gym Hallway Boy's BR @ (A)	SK	3.3	-	-	None	-	-
Gym Hallway Boy's BR @ (B)	SK	2.4	-	-	None	-	-
Gym Hallway Boy's BR @ (C)	SK	<1.0	-	-	None	-	-
Athletic Director's Office BR	SK	<1.0	-	-	None	-	-
Boy's LR Office	SK	<1.0	-	-	None	-	-
Boy's LR	WF	<1.0	-	-	None	-	-
Boy's LR BR @ (A)	SK	<1.0	-	-	None	-	-
Boy's LR BR @ (B)	SK	<1.0	-	-	None	-	-
Athletic Trainer Office	IM	<1.0	-	-	None	-	-
Custodian Office BR	SK	<2.5	-	-	None	-	-
Girls Pool LR Upstairs@ (A)	SS	5.9	-	-	None	-	-
<b>Girls Pool LR Downstairs@ (B)</b>	<b>SS</b>	<b>17</b>			<b>FR</b>	<b>SIGN</b>	-
Girls Pool LR	WF	<2.5	-	-	None	-	-
Girls Pool LR BR @ (A)	SK	<2.5	-	-	None	-	-
Girls Pool LR BR @ (B)	SK	<2.5	-	-	None	-	-
Pool Instructors Office	SK	<2.5	-	-	None	-	-
CPO Office	SK	3.7	-	-	None	-	-
Boys Pool LR	SS	<2.5	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Boys Pool LR	WF	<2.5	-	-	None	-	-
Boys Pool LR BR @ (A)	SK	<2.5	-	-	None	-	-
Boys Pool LR BR @ (B)	SK	4.2	-	-	None	-	-
Principal Office BR	SK	<2.5	-	-	None	-	-
Main Guidance	WF	<2.5	-	-	None	-	-
4th Fl. Mens BR RM B410	SK	<2.5	-	-	None	-	-
RM B412	SS	<2.5	-	-	None	-	-
4th Fl. Womens BR RM B414	SK	<2.5	-	-	None	-	-
3rd Fl. BR by RM B308	SK	<2.5	-	-	None	-	-
3rd Fl. Student Hall	SK	<2.5	-	-	None	-	-
3rd Fl. Student Hall	SS	12	-	-	None	-	-
3rd Fl. Boys BR @ (A)	SK	7.4	-	-	None	-	-
3rd Fl. Boys BR @ (B)	SK	<2.5	-	-	None	-	-
3rd Fl. Boys BR @ (C)	SK	<2.5	-	-	None	-	-
3rd Fl. Mens Staff BR	SK	4.1	-	-	None	-	-
CC By RM A3A	SS	3.3	-	-	None	-	-
<b>3rd Fl. Womens Staff BR @ (A)</b>	<b>SK</b>	<b>16</b>			<b>FR</b>	<b>SIGN</b>	-
3rd Fl. Womens Staff BR @ (B)	SK	3.8	-	-	None	-	-
3rd Fl. Girls BR @ (A)	SK	<2.5	-	-	None	-	-
3rd Fl. Girls BR @ (B)	SK	<2.5	-	-	None	-	-
3rd Fl. Girls BR @ (C)	SK	<2.5	-	-	None	-	-
Hallway by RM A305	WF	<2.5	-	-	None	-	-
RM A306 Teachers Station	SK	<2.5	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM A307 Teachers Station	SK	3.4	-	-	None	-	-
RM A308 Teachers Station	SK	11	-	-	None	-	-
<b>RM A308 @ (D)</b>	<b>SK</b>	<b>40</b>			<b>FR</b>	<b>SIGN</b>	-
RM A309 Teachers Station	SK	9.4	-	-	None	-	-
<b>RM A309 @ (A)</b>	<b>SK</b>	<b>122</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A309 @ (B)</b>	<b>SK</b>	<b>201</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A309 @ (C)</b>	<b>SK</b>	<b>327</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A309 @ (D)</b>	<b>SK</b>	<b>47</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A309 @ (E)</b>	<b>SK</b>	<b>38</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A309 @ (F)</b>	<b>SK</b>	<b>7668</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A309 @ (G)</b>	<b>SK</b>	<b>278</b>			<b>FR</b>	<b>SIGN</b>	-
RM A309 Prep RM	SK	7	-	-	None	-	-
RM A311 Teachers Station	SK	14	-	-	None	-	-
<b>RM A311 @ (C)</b>	<b>SK</b>	<b>23</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A311 @ (D)</b>	<b>SK</b>	<b>91</b>			<b>FR</b>	<b>SIGN</b>	-
RM A311 Biology Office	SK	4.5	-	-	None	-	-
<b>RM A312 Table @ (A)</b>	<b>SK</b>	<b>95</b>			<b>FR</b>	<b>SIGN</b>	-
<b>RM A312 Table @ (B)</b>	<b>SK</b>	<b>19</b>			<b>FR</b>	<b>SIGN</b>	-
A310 Teacher's Station	SK	4.1	-	-	None	-	-
<b>A310 Table 1 @ (A)</b>	<b>SK</b>	<b>22</b>			<b>FR</b>	<b>SIGN</b>	-
A310 Table 1 @ (B)	SK	<2.5	-	-	None	-	-
A310 Table 1 @ (C)	SK	3	-	-	None	-	-
A310 Table 1 @ (D)	SK	7.3	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
A205	WF	<2.5	-	-	None	-	-
A105	WF	<2.5	-	-	None	-	-
A114	WF	<2.5	-	-	None	-	-
Female Student BR by A2A @ (A)	SK	3.2	-	-	None	-	-
Female Student BR by A2A @ (B)	SK	4.9	-	-	None	-	-
Female Student BR by A2A @ (C)	SK	<2.5	-	-	None	-	-
Female Staff BR by A2A @ (A)	SK	2.9	-	-	None	-	-
<b>Female Staff BR by A2A @ (B)</b>	<b>SK</b>	<b>16</b>			<b>FR</b>	<b>SIGN</b>	-
CC A2A	SS	<2.5	-	-	None	-	-
Male Student BR by A2A @ (A)	SK	<2.5	-	-	None	-	-
Male Staff BR by A2A @ (A)	SK	7.4	-	-	None	-	-
<b>Male Staff BR by A2A @ (B)</b>	<b>SK</b>	<b>19</b>			<b>FR</b>	<b>SIGN</b>	-
Male Staff BR by A2A @ (C)	SK	5.8	-	-	None	-	-
CC 217	SS	<2.5	-	-	None	-	-
Male Student BR by 1A1 @ (B)	SK	<2.5	-	-	None	-	-
Male Staff BR by 1A1 @ (A)	SK	<2.5	-	-	None	-	-
Male Staff BR by 1A1 @ (B)	SK	2.5	-	-	None	-	-
Male Staff BR by 1A1 @ (C)	SK	9	-	-	None	-	-
CC 211	SS	<2.5	-	-	None	-	-
Female Student BR by 1A1 @ (A)	SK	<2.5	-	-	None	-	-
Female Student BR by 1A1 @ (B)	SK	<2.5	-	-	None	-	-
Female Student BR by 1A1 @ (C)	SK	<2.5	-	-	None	-	-
Female Staff BR by 1A1 @ (A)	SK	<2.5	-	-	None	-	-



**Lead in Drinking Water Test Results**

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Female Staff BR by 1A1 @ (B)	SK	<2.5	-	-	None	-	-
CC 1A1	SS	<2.5	-	-	None	-	-
RM 116 @ (B)	SK	<2.5	-	-	None	-	-
RM 116 @ (D)	SK	<2.5	-	-	None	-	-
A116 / 118	SK	<2.5	-	-	None	-	-
A101	SK	<2.5	-	-	None	-	-
Faculty Room, Coffee Filler	SP	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Handwash by Freezer	SK	<1.0	-	-	None	-	-
Kitchen 3 Compartment (Left)	SK	<1.0	-	-	None	-	-
Kitchen 3 Compartment (Right)	SK	<1.0	-	-	None	-	-
Kitchen Pot Filler	SP	<1.0	-	-	None	-	-
Kitchen Sink by SS	SK	<1.0	-	-	None	-	-
Kitchen 3 Compartment (Left)	SS	1.3	-	-	None	-	-
Kitchen BR	SK	<1.0	-	-	None	-	-
Kitchen Handwash by Slicer	SK	<1.0	-	-	None	-	-
Women's BR by Cafe @ (A)	SK	<1.0	-	-	None	-	-
Women's BR by Cafe @ (B)	SK	<1.0	-	-	None	-	-
Boy's BR at Main Hall @ (B)	SK	<1.0	-	-	None	-	-
Staff BR at Main Hall @ (A)	SK	<1.0	-	-	None	-	-
Staff BR at Main Hall @ (B)	SK	<1.0	-	-	None	-	-
CC by Main Hall	SS	<1.0	-	-	None	-	-
Hall by Boy's LR	WF	<1.0	-	-	None	-	-
Faculty Lounge	SK	<1.0	-	-	None	-	-
Women's Faculty BR @ (A)	SK	<1.0	-	-	None	-	-
Women's Faculty BR @ (B)	SK	<1.0	-	-	None	-	-
Men's Faculty BR @ (A)	SK	<1.0	-	-	None	-	-
Men's Faculty BR @ (B)	SK	<1.0	-	-	None	-	-
CC by District	SS	<1.0	-	-	None	-	-
Room 140 @ (A)	SK	<1.0	-	-	None	-	-
Room 140 @ (B)	SK	4.7	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 140 @ (C)	SK	<1.0	-	-	None	-	-
Room 140 @ (D)	SK	<1.0	-	-	None	-	-
Boy's LR BR @ (A)	SK	<1.0	-	-	None	-	-
Boy's LR BR @ (B)	SK	<1.0	-	-	None	-	-
Boy's LR BR @ (C)	SK	<1.0	-	-	None	-	-
Principal BR	SK	<1.0	-	-	None	-	-
Conference RM	SK	<1.0	-	-	None	-	-
Nurse's Office BR-RM 1 @ (A)	SK	<1.0	-	-	None	-	-
Nurse's Office BR-RM 2 @ (B)	SK	<1.0	-	-	None	-	-
Nurse's Office	SK	<1.0	-	-	None	-	-
2nd Fl. Girl's BR @ (A)	SK	<1.0	-	-	None	-	-
2nd Fl. Girl's BR @ (B)	SK	<1.0	-	-	None	-	-
2nd Fl. Boy's BR by Gym @ (B)	SK	<1.0	-	-	None	-	-
Room 101 Teachers Station @ (A)	SK	2.6	-	-	None	-	-
Room 101 Teachers Station @ (B)	SK	2.9	-	-	None	-	-
Hall by RM 7009 Guidance	WF	<1.0	-	-	None	-	-
Art RM 106 @ (A)	SK	6.2	-	-	None	-	-
Art RM 106 @ (B)	SK	4.5	-	-	None	-	-
Art RM 106 Table	SK	<1.0	-	-	None	-	-
CC RM 7004	SS	<1.0	-	-	None	-	-
<b>Room 111 Teachers Station @ (A)</b>	<b>SK</b>	<b>31</b>			<b>FR</b>	<b>CAP</b>	<b>&lt;1.0</b>
<b>Room 111 Teachers Station @ (B)</b>	<b>SK</b>	<b>57</b>			<b>FR</b>	<b>CAP</b>	<b>49 (11/11/2016)</b>
<b>Room 111 Table 1 @ (A)</b>	<b>SK</b>	<b>26</b>			<b>FR</b>	<b>CAP</b>	<b>1.6</b>

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 111 Table 1 @ (B)	SK	12	-	-	None	-	-
<b>Room 111 Table 2 @ (A)</b>	<b>SK</b>	<b>16</b>			<b>FR</b>	<b>CAP</b>	<b>&lt;1.0</b>
Room 111 Table 2 @ (B)	SK	9.5	-	-	None	-	-
Room 111 Table 3 @ (A)	SK	1.1	-	-	None	-	-
Room 111 Table 3 @ (B)	SK	2.3	-	-	None	-	-
Room 116 Teachers Table @ (A)	SK	5.5	-	-	None	-	-
<b>Room 116 Teachers Table @ (B)</b>	<b>SK</b>	<b>170</b>			<b>FR</b>	<b>CAP</b>	<b>25 (11/11/2016)</b>
Hall by RM 7033	WF	<1.0	-	-	None	-	-
Room 121 @ (A)	SK	<1.0	-	-	None	-	-
Room 121 @ (B)	SK	<1.0	-	-	None	-	-
Room 7024 Vestibule Women's BR	SK	<1.0	-	-	None	-	-
Room 7024 Vestibule Men's BR	SK	<1.0	-	-	None	-	-
Hall by RM 7020 Suit 6	WF	<1.0	-	-	None	-	-
Room 126 Teachers Station @ (A)	SK	4.4	-	-	None	-	-
CC by Band RM	SS	<1.0	-	-	None	-	-
Sup. Office BR	SK	<1.0	-	-	None	-	-
Basement Women's BR @ (A)	SK	7.7	-	-	None	-	-
Basement Women's BR @ (B)	SK	2.9	-	-	None	-	-
Basement Women's BR @ (C)	SK	<1.0	-	-	None	-	-
Basement Women's BR @ (D)	SK	4.9	-	-	None	-	-
CC Basement	SS	9.2	-	-	None	-	-
Basement Hallway	WF	2.4	-	-	None	-	-
Basement Men's BR @ (A)	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Basement Men's BR @ (B)	SK	1.4	-	-	None	-	-
Basement Men's BR @ (C)	SK	11	-	-	None	-	-
Girl's BR by RM 7005 @ (A)	SK	10	-	-	None	-	-
Girl's BR by RM 7005 @ (B)	SK	5.9	-	-	None	-	-
<b>Girl's BR by RM 7005 @ (C)</b>	<b>SK</b>	<b>20</b>			<b>FR</b>	<b>SIGN</b>	<b>16 (11/11/2016)</b>
<b>Girl's BR by RM 7005 @ (D)</b>	<b>SK</b>	<b>78</b>			<b>FR</b>	<b>SIGN</b>	<b>5.7</b>
Girl's BR by RM 7005 @ (E)	SK	10	-	-	None	-	-
Girl's LR BR @ (A)	SK	1.1	-	-	None	-	-
Girl's LR BR @ (B)	SK	6.9	-	-	None	-	-
Girl's LR BR @ (C)	SK	<1.0	-	-	None	-	-
Room 7015	SK	1.8	-	-	None	-	-
Room 7015 BR	SK	6.1	-	-	None	-	-
Room 901 BR	SK	4.2	-	-	None	-	-
Room 902 BR	SK	<1.0	-	-	None	-	-
Room 903 BR	SK	<1.0	-	-	None	-	-
Room 904 BR	SK	<1.0	-	-	None	-	-
Room 905 Girl's BR	SK	2.9	-	-	None	-	-
Room 905 Boy's BR	SK	<1.0	-	-	None	-	-
Room 907 Girl's BR	SK	<1.0	-	-	None	-	-
Room 907 Boy's BR	SK	<1.0	-	-	None	-	-
Room 909 Girl's BR	SK	<1.0	-	-	None	-	-
Room 909 Boy's BR	SK	<1.0	-	-	None	-	-
Room 911 - Left @ (A)	SK	<1.0	-	-	None	-	-

**Lead in Drinking Water Test Results**

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 911 - Right @ (B)	SK	<1.0	-	-	None	-	-
Room 913 Boy's (Right)	SK	<1.0	-	-	None	-	-
Room 913 Boy's (Left)	SK	<1.0	-	-	None	-	-
Girl's LR CC	SS	3.9	-	-	None	-	-

### Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Portable M BR	SK	<1.0	-	-	None	-	-
Portable O BR	SK	<1.0	-	-	None	-	-
Portable P BR	SK	<1.0	-	-	None	-	-
Portable N BR	SK	<1.0	-	-	None	-	-
Portable G BR	SK	<1.0	-	-	None	-	-
Portable H BR	SK	<1.0	-	-	None	-	-
Portable F BR	SK	<1.0	-	-	None	-	-
Portable E BR	SK	<1.0	-	-	None	-	-
Portable A/B BR	SK	<1.0	-	-	None	-	-
Portable C BR	SK	<1.0	-	-	None	-	-
Portable D BR	SK	<1.0	-	-	None	-	-
Portable K BR	SK	<1.0	-	-	None	-	-
Portable J BR	SK	<1.0	-	-	None	-	-
Portable L BR	SK	<1.0	-	-	None	-	-
Portable I BR	SK	<1.0	-	-	None	-	-
RM 6	WF	<1.0	-	-	None	-	-
RM 6	SK	<1.0	-	-	None	-	-
Hallway by RM 7	WF	<1.0	-	-	None	-	-
RM 5	SK	<1.0	-	-	None	-	-
RM 7	WF	<1.0	-	-	None	-	-
RM 7	SK	<1.0	-	-	None	-	-
Boys BR by RM 7	SK	<1.0	-	-	None	-	-
Girls BR by RM 7	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
CC by RM 7	SS	<1.0	-	-	None	-	-
Kitchen	SK	<1.0	-	-	None	-	-
Nurse BR	SK	<1.0	-	-	None	-	-
Teachers Lounge	SK	<1.0	-	-	None	-	-
Teachers Lounge BR	SK	<1.0	-	-	None	-	-
RM 1	WF	<1.0	-	-	None	-	-
RM 1	SK	<1.0	-	-	None	-	-
RM 4	WF	<1.0	-	-	None	-	-
RM 4	SK	<1.0	-	-	None	-	-
Hallway by RM 2	WF	<1.0	-	-	None	-	-
RM 2	WF	<1.0	-	-	None	-	-
RM 2	SK	<1.0	-	-	None	-	-
RM 3	WF	<1.0	-	-	None	-	-
RM 3	SK	<1.0	-	-	None	-	-



### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen	SK	1.3	-	-	None	-	-
Hallway by RM 11	WF	<1.0	-	-	None	-	-
Boys BR by RM 11 @ (A)	SK	<1.0	-	-	None	-	-
Boys BR by RM 11 @ (B)	SK	1.5	-	-	None	-	-
Girls BR by RM 19 @ (A)	SK	<1.0	-	-	None	-	-
Girls BR by RM 19 @ (B)	SK	1.9	-	-	None	-	-
Hallway by RM 19	WF	<1.0	-	-	None	-	-
CC by RM 19	SS	<1.0	-	-	None	-	-
RM 18	SK	1.9	-	-	None	-	-
Portable B BR	SK	<1.0	-	-	None	-	-
Portable A BR	SK	1.1	-	-	None	-	-
Mens BR by Conference RM	SK	<1.0	-	-	None	-	-
Womens BR by Conference RM	SK	<1.0	-	-	None	-	-
Nurse Office	SK	2	-	-	None	-	-
Main Office	SK	2.7	-	-	None	-	-
CC by Main Office	SS	<1.0	-	-	None	-	-
Portable C	SK	<1.0	-	-	None	-	-
Portable D	SK	<1.0	-	-	None	-	-
Girls BR by RM 4 @ (A)	SK	<1.0	-	-	None	-	-
Girls BR by RM 4 @ (B)	SK	<1.0	-	-	None	-	-
BR by RM 8A	SK	<1.0	-	-	None	-	-
Boys BR by RM 8A @ (A)	SK	<1.0	-	-	None	-	-
Boys BR by RM 8A @ (B)	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Hallway by RM 8A	WF	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen	SK	2.5	-	-	None	-	-
Kitchen BR	SK	<1.0	-	-	None	-	-
RM 9 BR	SK	5	-	-	None	-	-
RM 10 BR	SK	<1.0	-	-	None	-	-
RM 8 BR	SK	<1.0	-	-	None	-	-
RM 6 BR	SK	2.7	-	-	None	-	-
RM 7 BR	SK	<1.0	-	-	None	-	-
RM 5 BR	SK	<1.0	-	-	None	-	-
RM 11 BR	SK	<1.0	-	-	None	-	-
RM 12 BR	SK	<1.0	-	-	None	-	-
RM 2	SK	4.9	-	-	None	-	-
RM 3 BR	SK	<1.0	-	-	None	-	-
Hallway by RM 3	WF	<1.0	-	-	None	-	-
Boys BR by RM 3	SK	<1.0	-	-	None	-	-
Girls BR by RM 3	SK	<1.0	-	-	None	-	-
<b>RM 1 Bubbler</b>	<b>WF</b>	<b>51</b>			<b>FR</b>	<b>Completed FR</b>	<b>&lt;1.0</b>
RM 1	SK	7.7	-	-	None	-	-
CC by RM 3	SS	5.1	-	-	None	-	-
Principal	SK	6.2	-	-	None	-	-
Ladies BR by Main Office	SK	<1.0	-	-	None	-	-
RM 4	SK	3.3	-	-	None	-	-
MP Media BR	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
<b>2nd Fl. CC</b>	<b>SS</b>	<b>2700</b>			<b>FR</b>	<b>SIGN</b>	-
2nd Fl. Men/Women BR @ (A)	SK	6.2	-	-	None	-	-
2nd Fl. Men/Women BR @ (B)	SK	<2.5	-	-	None	-	-
Main Fl. BR	SK	<2.5	-	-	None	-	-
Registration Hall BR	SK	<2.5	-	-	None	-	-
<b>Main Fl. CC</b>	<b>SS</b>	<b>1600</b>			<b>FR</b>	<b>SIGN</b>	-
Lounge @ (A)	SK	<2.5	-	-	None	-	-
Lounge @ (B)	SK	<2.5	-	-	None	-	-
Lounge @ (C)	SK	3.7	-	-	None	-	-
<b>Basement Book RM @ (A)</b>	<b>SK</b>	<b>870</b>			<b>FR</b>	<b>SIGN</b>	-
<b>Basement Book RM @ (B)</b>	<b>SK</b>	<b>34</b>			<b>FR</b>	<b>SIGN</b>	-
Basement Book RM @ (C)	SK	4.3	-	-	None	-	-
<b>Basement CC</b>	<b>SS</b>	<b>88</b>			<b>FR</b>	<b>SIGN</b>	-
Basement Men/Women BR	SK	<2.5	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girl's BR by Cafeteria @ (A)	SK	3.7	-	-	None	-	-
Girl's BR by Cafeteria @ (B)	SK	1.6	-	-	None	-	-
Boy's BR by Cafeteria @ (A)	SK	2.7	-	-	None	-	-
Boy's BR by Cafeteria @ (B)	SK	<1.0	-	-	None	-	-
Kitchen Prep	SK	8.8	-	-	None	-	-
Kitchen Handwash	SK	11	-	-	None	-	-
Kitchen Dishwasher @ (A)	SK	3	-	-	None	-	-
Kitchen Dishwasher @ (B)	SK	1.8	-	-	None	-	-
Kitchen Handwash (Left)	SK	11	-	-	None	-	-
Hallway by RM 14 (High)	WF	<1.0	-	-	None	-	-
Hallway by RM 14 (Low)	WF	<1.0	-	-	None	-	-
CC by RM 14	SS	5.2	-	-	None	-	-
RM 14	WF	<1.0	-	-	None	-	-
RM 14	SK	<1.0	-	-	None	-	-
RM 15	WF	<1.0	-	-	None	-	-
RM 15	SK	<1.0	-	-	None	-	-
RM 16	WF	<1.0	-	-	None	-	-
RM 16	SK	<1.0	-	-	None	-	-
RM 17	WF	<1.0	-	-	None	-	-
RM 17	SK	<1.0	-	-	None	-	-
RM 18	WF	<1.0	-	-	None	-	-
RM 18	SK	1.1	-	-	None	-	-
RM 19	SK	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Rm 26	WF	<1.0	-	-	None	-	-
RM 26	SK	<1.0	-	-	None	-	-
RM 27	WF	<1.0	-	-	None	-	-
RM 27	SK	<1.0	-	-	None	-	-
Women's BR by RM 27	SK	<1.0	-	-	None	-	-
RM 28	WF	<1.0	-	-	None	-	-
RM 28	SK	<1.0	-	-	None	-	-
RM 24	WF	<1.0	-	-	None	-	-
RM 24	SK	<1.0	-	-	None	-	-
RM 31	WF	<1.0	-	-	None	-	-
RM 31	SK	<1.0	-	-	None	-	-
<b>Boy's BR by RM 31 @ (A)</b>	<b>SK</b>	<b>16</b>			<b>FR</b>	<b>SIGN</b>	<b>6.5</b>
Boy's BR by RM 31 @ (B)	SK	5.6	-	-	None	-	-
Boy's BR by RM 31 @ (C)	SK	3.4	-	-	None	-	-
CC by RM 31	SS	3.5	-	-	None	-	-
RM 22	WF	<1.0	-	-	None	-	-
RM 22	SK	<1.0	-	-	None	-	-
Hallway by RM 22 (High)	WF	<1.0	-	-	None	-	-
Hallway by RM 22 (Low)	WF	<1.0	-	-	None	-	-
RM 32	WF	<1.0	-	-	None	-	-
RM 32	SK	<1.0	-	-	None	-	-
RM 33	WF	1.5	-	-	None	-	-
RM 33	SK	1	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Men's BR by RM 33	SK	<1.0	-	-	None	-	-
RM 34	WF	<1.0	-	-	None	-	-
RM 34	SK	<1.0	-	-	None	-	-
RM 20	WF	<1.0	-	-	None	-	-
RM 20	SK	<1.0	-	-	None	-	-
Nurse's Office	SK	<1.0	-	-	None	-	-
Nurse's BR	SK	2	-	-	None	-	-
RM 4	WF	<1.0	-	-	None	-	-
RM 4	SK	<1.0	-	-	None	-	-
RM 5	WF	<1.0	-	-	None	-	-
RM 5	SK	<1.0	-	-	None	-	-
Women's BR by RM 5	SK	<1.0	-	-	None	-	-
RM 3	WF	1.2	-	-	None	-	-
RM 3	SK	<1.0	-	-	None	-	-
RM 7	WF	<1.0	-	-	None	-	-
RM 7	SK	<1.0	-	-	None	-	-
Main Office	SK	1.3	-	-	None	-	-
Girl's BR by Main Office @ (A)	SK	<1.0	-	-	None	-	-
Girl's BR by Main Office @ (B)	SK	<1.0	-	-	None	-	-
Girl's BR by Main Office @ (C)	SK	<1.0	-	-	None	-	-
CC by Main Office	SS	4	-	-	None	-	-
Hallway by RM 8 (High)	WF	<1.0	-	-	None	-	-
Hallway by RM 8 (Low)	WF	<1.0	-	-	None	-	-

### Lead in Drinking Water Test Results

As of 12/5/16

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 6	WF	<1.0	-	-	None	-	-
RM 6	SK	1.1	-	-	None	-	-
RM 13	WF	<1.0	-	-	None	-	-
RM 13	SK	1.7	-	-	None	-	-
RM 12	WF	2.3	-	-	None	-	-
RM 12	SK	1	-	-	None	-	-
RM 11	WF	<1.0	-	-	None	-	-
RM 11	SK	<1.0	-	-	None	-	-
RM 10	WF	<1.0	-	-	None	-	-
RM 10	SK	<1.0	-	-	None	-	-
Men's BR by RM 10	SK	<1.0	-	-	None	-	-
CC at Lower Level	SS	3.6	-	-	None	-	-
Lower Level Men's BR	SK	<1.0	-	-	None	-	-
Lower Level Women's BR	SK	<1.0	-	-	None	-	-
RM L8	WF	<1.0	-	-	None	-	-
RM L8	SK	<1.0	-	-	None	-	-
Hallway by RM L8 (Low)	WF	<1.0	-	-	None	-	-
Hallway by RM L8 (High)	WF	<1.0	-	-	None	-	-
RM L2	WF	<1.0	-	-	None	-	-
RM L2	SK	<1.0	-	-	None	-	-
RM L9	WF	<1.0	-	-	None	-	-
RM L9	SK	<1.0	-	-	None	-	-
Custodian Break RM	SK	<1.0	-	-	None	-	-